

# Dhanbad Municipal Corporation

## SITE VISIT REPORT

### Proposal Details


Owner Name : RAM KUMAR AGARWALLA HUF MUKESH	Site Visit Date : 01 February, 2022
Applicant Name : KUMAR AGARWAL AND LALIT KUMAR AGARWALLA	File No. : DMC/BP/0281/W23/2019/ALT2
Ward No. : W23	Case Type : Addition Alteration
Thana No. : 12	Plot No. : OLD NO -
Road No. / Name : GANGA APARTMENT , SHANTI BHAWAN , JHARIA ROAD, BANK MORE DHANBAD	Registration No. : 182, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199 & 200 NEW NO - 200, 201, 202, 203, 205, 278 & 280



### Site Visit Checklist

#	Description	As On Site	Objection	Remark
1.	Whether Existing at Site	Yes		
2.	Whether connected with an existing public road	Yes		
3.	Status of road	Public		
4.	Nature of Road	Blacktop		
5.	Width of approach road	30.47		
6.	Whether road side drain exists	Yes		
7.	if Whether road side drain exists is Yes - Width	1.21		
8.	if Whether road side drain exists is Yes - Nature	Concrete		
9.	if Whether road side drain exists is Yes - Whether connected to	Public Drain		
10.	Whether the site is at road junction	No		
11.	Level of site in relation to approach road	1		
12.	Whether the area is subject to	NA		
13.	Whether the locality is	Developing		
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	30		
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	1		
16.	Whether the Site is vacant	No		
17.	if Whether the Site is vacant No - Stage of construction	3		
18.	if Whether the Site is vacant No - No of Storey	3		
19.	if Whether the Site is vacant No - Nature of construction	RCC		
20.	if Whether the Site is vacant No - Sketch enclosed at page	Yes		
21.	Plot size (As per measurement)(In Sqmt)	5040.1		
22.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
23.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	yes		
24.	Any other information.	no		
25.	Verified the Amins report with/without site inspection and found correct	Yes		
26.	Land Use	Commercial		
27.	Road	Yes		
28.	Sewerage	No		
29.	Drainage	Yes		
30.	Water facility	Yes		


31.	Availability of drain	Yes		
32.	Telephone	Yes		
33.	Electricity	Yes		
34.	Dealing with inflammable/chemical	No		
35.	Occupancy	No		
36.	EAST	HOUSE		
37.	WEST	BOUNDARY WALL		
38.	NORTH	ROAD		DHANBAD GOVINDPUR MAIN ROAD
39.	SOUTH	PLOT		
40.	Length of the Road(In Mtr.)	Exceeding 1000 meter		
41.	Existing Width of the Road(In Mtr.)	30.47		
42.	Proposed Width of the Road as per Master Plan(In Mtr.)	30.47		
43.	Width of the RoadWidening(In Mtr.)	0		
44.	Plot area (As per deed)	5040.16		

### Site Visit Photographs :









































































8955/Chand, Chhatrapati Nagar, Dhanbad, Jharkhand 826005, India

Dhanbad  
Jharkhand  
India

2022-02-25(Fri) 04:29(pm)

31°C  
88°F

Google



8955/Chand, Chhatrapati Nagar, Dhanbad, Jharkhand 826005, India

Dhanbad  
Jharkhand  
India

2022-02-25(Fri) 04:30(pm)

31°C  
88°F

Google



8955/Chand, Chhatrapati Nagar, Dhanbad, Jharkhand 826005, India

Dhanbad  
Jharkhand  
India



2022-02-25(Fri) 04:30(pm)

31°C  
88°F




Google









































**Recommendation** : Verified & found Ok

**Remark** : SITE INSPECTION DONE AND FOUND OKAY. SITE VISIT REPORT IS ATTACHED. PLEASE CHECK FOR FURTHER APPROVAL.

Bikash Kumar  
Junior Engg