Dhanbad Municipal Corporation

SITE VISIT REPORT

| Proposal Details | | | | | | |
|------------------|----------------------|------------------|------------------------------|--|--|--|
| Owner Name | : RAJ KARAN PANDIT | Site Visit Date | : 09 January, 2021 | | | |
| Applicant Name | : PARTHA - PAL | File No. | : DMC/BP/0298/W24/2020 | | | |
| Ward No. | : W24 | Case Type | : New | | | |
| Thana No. | : 12 | Plot No. | 2157 , 2129(new : 2951,2953) | | | |
| Road No. / Name | : KOLAKUSMA,DHANBAD. | Registration No. | : DMC/ENG/0021/2016 | | | |
| | | | | | | |

| | Site Visit Checklist | | | | | |
|-----|---|-------------|-----------|--------|--|--|
| # | Description | As On Site | Objection | Remark | | |
| 1. | Whether Existing at Site | Yes | | | | |
| 2. | Whether connected with an existing public road | Yes | | | | |
| 3. | Status of road | Public | | | | |
| 4. | Nature of Road | Kutchha | | | | |
| 5. | Width of approach road | 4.6 | | | | |
| 6. | Whether road side drain exists | No | | | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 250 | | | | |
| 8. | if Whether road side drain exists is No - easibility to connect | No | | | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | NO | | | | |
| 10. | Whether the site is at road junction | No | | | | |
| 11. | Level of site in relation to approach road | 0.001 | | | | |
| 12. | Whether the area is subject to | NA | | | | |
| 13. | Whether the locality is | Developing | | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 450 | | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 150 | | | | |
| 16. | Whether the Site is vacant | Yes | | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 169.15 | | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | YES | | | | |
| 20. | Any other information. | NO | | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | | |
| 22. | Land Use | Residential | | | | |
| 23. | Road | Yes | | | | |
| 24. | Sewerage | No | | | | |
| 25. | Drainage | No | | | | |
| 26. | Water facility | No | | | | |
| 27. | Availability of drain | Yes | | | | |
| 28. | Telephone | No | | | | |
| 29. | Electricity | Yes | | | | |
| 30. | Dealing with inflammable/chemical | No | | | | |
| | | | | | | |

| 31. | Occupancy | No |
|-----|--|-----------------|
| 32. | EAST | PLOT & BOUNDARY |
| 33. | WEST | ROAD |
| 34. | NORTH | PLOT |
| 35. | SOUTH | ROAD |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.) | 4.6 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 4.6 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 171.24 |

Site Visit Photographs :









Recommendation : Verified & found Ok

Remark : ward number is wrong please change ward number in all documents. in affidavit write measuring area. Site Inspection done and found okay. Site visit report is attached. Please check for further approval.

Mahesh Bhagat Junior Engg