Dhanbad Municipal Corporation

SITE VISIT REPORT

Dror	osal Details									
-				07.14	22					
	er Name : ARBIND KUMAR SINHA, KUMAR BIPIN icant Name : Kushjee Pandey		Site Visit Date File No.	: 07 March, 2022 : DMC/BP/0041/W20/2020						
Ward No. : W20		(Case Type	: New						
Thana No. : 05		Plot No. OLD-448, NEW-835								
Road No. / Name : Kenduadih coaliary, Po- kusunda, Ps- Kenduadih,Dhanbad			Registration No.	: DMC/ARC/002	27/2017					
	Site Visit Checklist									
#	Description	4	s On Site	Objection	Remark					
1.	Whether Existing at Site	Yes								
2.	Whether connected with an existing public road	Yes								
3.	Status of road	Public	2							
4.	Nature of Road	Black	top							
5.	Width of approach road	6.1								
6.	Whether road side drain exists	No								
7.	if Whether road side drain exists is No - Distance from nearest drain	100m	I							
	if Whether road side drain exists is No - easibility to connect	No								
	if Whether road side drain exists is No - Scope of widening of road	no								
	Whether the site is at road junction	No								
	Level of site in relation to approach road	0.01m								
12.	Whether the area is subject to	NA								
	Whether the locality is	Developing								
	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	5m								
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	3m								
16.	Whether the Site is vacant				Old PERMANENT Structure is presnt ON SITE of plot.					
17.	Plot size (As per measurement)(In Sqmt)	1330.2								
18.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No								
19.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	yes								
20.	Any other information.	NO								
21.	Verified the Amins report with/without site inspection and found correct	Yes								
22.	Land Use	Commercial								
23.	Road	Yes								
24.	Sewerage	No								
25.	Drainage	No								
26.	Water facility	Yes								
27.	Availability of drain	Yes								
28.	Telephone	Yes								
29.	Electricity	Yes								

30.	Dealing with inflammable/chemical	No	
31.	Occupancy	No	
32.	EAST	BOUNDARY WALL AND SHOP	
33.	WEST	BOUNDARY WALL AND PLOT	
34.	NORTH	ROAD	
35.	SOUTH	PLOT	
36.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter	
37.	Existing Width of the Road(In Mtr.)	6.1	Physical Wall to Wall clear distance available at the site
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	6.1	
39.	Width of the RoadWidening(In Mtr.)	0	
40.	Plot area (As per deed)	1335.94	

Site Visit Photographs :















Bishunpur Regener Oriventer Distored Jaarhoad Jaarhoad Jaarhoad VIP C Ó
















































Recommendation : Verified & found Ok Remark : SITE INSPECTION DONE AND FOUND OKAY. SITE VISIT REPORT IS ATTACHED. PLEASE CHECK FOR FURTHER APPROVAL.

Bikash Kumar Junior Engg