

Dhanbad Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : SMT UMRAWATI DEVI	Site Visit Date : 11 August, 2020
Applicant Name : ASHOK KUMAR	File No. : DMC/BP/0165/W21/2020
Ward No. : W21	Case Type : New
Thana No. : 03	Plot No. : 368(N) ,339(0)
Road No. / Name :	Registration No. : DMC/ENG/0011/2017

Site Visit Checklist

#	Description	As On Site	Objection	Remark
1.	Whether Existing at Site	Yes		
2.	Whether connected with an existing public road	No		
3.	Status of road	Public		
4.	Nature of Road	Kutchha		
5.	Width of approach road	3.6		
6.	Whether road side drain exists	No		
7.	if Whether road side drain exists is No - Distance from nearest drain	200		
8.	if Whether road side drain exists is No - easibility to connect	No		
9.	if Whether road side drain exists is No - Scope of widening of road	NA		
10.	Whether the site is at road junction	Yes		
11.	Level of site in relation to approach road	.01		
12.	Whether the area is subject to	NA		
13.	Whether the locality is	Developing		
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	200		
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	50		
16.	Whether the Site is vacant	Yes		
17.	Plot size (As per measurement)(In Sqmt)	222.5		
18.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
19.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Yes		
20.	Any other information.	NA		
21.	Verified the Amins report with/without site inspection and found correct	Yes		
22.	Land Use	Residential		
23.	Road	No		
24.	Sewerage	No		
25.	Drainage	No		
26.	Water facility	No		
27.	Availability of drain	No		
28.	Telephone	No		
29.	Electricity	No		
30.	Dealing with inflammable/chemical	No		

31.	Occupancy	No		
32.	EAST	Proposed Road		
33.	WEST	Vacant Plot		
34.	NORTH	Proposed Road		
35.	SOUTH	Vacant Plot		
36.	Length of the Road(In Mtr.)	Up to 50 meter		
37.	Existing Width of the Road(In Mtr.)	3.6		
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	3.6		
39.	Width of the RoadWidening(In Mtr.)	0		
40.	Plot area (As per deed)	224.7		

Site Visit Photographs :





Site Inspection

1. Plot No.	306/2/214/215/196	Date	/ / 2020
2. Owner Name	UMRANATH DEVI		
3. ITP	A CHOKK KUMAR		

4. Schedule of Boundaries

East	ROAD - 13'0" BROAD
West	W.M. NIZ
North	16' ROAD
South	SAME MAT

Plot Address: **BARAMPALI, DISHA ROAD**

Mouza: **BARAMPALI - 03**

Khata: **55(0) 514(N)**

Plot: **329(0) 56(N)**

Area: **5.55 Decimals**

Site Inspection as per Site visit

Road width & Road type: _____

Electric: **YES**

Drain: **NO**

Soil: **NO**

Landmark: _____

The above mentioned information about the plot is true and Site shown to it is same for which I had applied for (MBA approval)

Signature of Land owner: _____

Signature of ITP staff: _____

Recommendation : Verified & found Ok

Remark : Site Inspection done and found Okay. Site visit report is attached. Please check for further approval.

Deepak Kumar Pandit
Junior Engg