Dhanbad Municipal Corporation

SITE VISIT REPORT

| Proposal Details | | | | | | | |
|------------------|--|------------------|-------------------------------|--|--|--|--|
| Owner Name | : Sri. Shankar Prasad Singh and Others | Site Visit Date | : 18 August, 2020 | | | | |
| Applicant Name | : PIYUSH KANTI SINGH | File No. | : DMC/BP/0170/W23/2020 | | | | |
| Ward No. | : W23 | Case Type | : New | | | | |
| Thana No. | : 12 | Plot No. | 1858 (Old), New Plot No 2419 | | | | |
| Road No. / Name | : Kolakusma Saraidhela Dhanbad | Registration No. | : DMC/ENG/0020/2016 | | | | |
| , | | 5 | | | | | |

| | Site Visit | Checklist | | |
|-----|---|-------------|-----------|------------------------------------|
| # | Description | As On Site | Objection | Remark |
| 1. | Whether Existing at Site | Yes | | |
| 2. | Whether connected with an existing public road | Yes | | Kutchha road with water logging |
| 3. | Status of road | Public | | |
| 4. | Nature of Road | Kutchha | | |
| 5. | Width of approach road | 4.1m | | |
| 6. | Whether road side drain exists | No | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 35m | | |
| 8. | if Whether road side drain exists is No - easibility to connect | No | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | na | | |
| 10. | Whether the site is at road junction | No | | |
| 11. | Level of site in relation to approach road | 0.1 | | |
| 12. | Whether the area is subject to | NA | | |
| 13. | Whether the locality is | Developing | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 120m | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 40m | | |
| 16. | Whether the Site is vacant | Yes | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 88.6 | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | |
| | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | yes | | |
| 20. | Any other information. | na | | |
| | Verified the Amins report with/without site inspection and found correct | Yes | | |
| 22. | Land Use | Residential | | |
| 23. | Road | Yes | | |
| 24. | Sewerage | No | | |
| 25. | Drainage | No | | |
| 26. | Water facility | No | | |
| 27. | Availability of drain | No | | |
| 28. | Telephone | No | | |
| 29. | Electricity | No | | |
| 30. | Dealing with inflammable/chemical | No | | |

| 31. | Occupancy | No |
|-----|--|---------------------------------------|
| 32. | EAST | house of rashmi shika |
| 33. | WEST | under construction of bharat singh |
| 34. | NORTH | vacant plot |
| 35. | SOUTH | road 16 feet |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.) | 4.8 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 3.6 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 88.6 |

Site Visit Photographs :









Recommendation : Verified & found Ok Remark : Site Inspection done and found okay.Site visit report is attached.Please check for further approval.

> Deepak Kumar Pandit Junior Engg