Dhanbad Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : SRI RAM NIVAS MALI Site Visit Date : 20 March, 2020

Applicant Name : TULSI CHAUDHARI File No. : DMC/BP/0085/W20/2020

Ward No. : W20 Case Type : New

Thana No. : 05 Plot No. (OLD- 262),(NEW- 451)

Road No. / Name : DURGAMANDIR ROAD Registration No. : DMC/STU/0005/2017

Site Visit Checklist							
#	Description	As On Site	Objection	Remark			
1.	Whether Existing at Site	Yes					
2.	Whether connected with an existing public road	Yes					
3.	Status of road	Public					
4.	Nature of Road	Kutchha					
5.	Width of approach road	3.6m					
6.	Whether road side drain exists	No					
7.	if Whether road side drain exists is No - Distance from nearest drain	250m					
	if Whether road side drain exists is No - easibility to connect	No					
9.	if Whether road side drain exists is No - Scope of widening of road	no					
10.	Whether the site is at road junction	No					
11.	Level of site in relation to approach road	0.01m					
12.	Whether the area is subject to	NA					
13.	Whether the locality is	Developing					
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	200					
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	50m					
16.	Whether the Site is vacant	Yes					
17.	Plot size (As per measurement)(In Sqmt)	127.36					
	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No					
19.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	yes					
20.	Any other information.	200m from CMRI back gate					
21.	Verified the Amins report with/without site inspection and found correct	Yes					
22.	Land Use	Residential					
23.	Road	Yes					
24.	Sewerage	No					
25.	Drainage	No					
26.	Water facility	No					
27.	Availability of drain	No					
28.	Telephone	No					
29.	Electricity	No					
30.	Dealing with inflammable/chemical	No					

Page 1 of 4 Printed on: 12 June, 2020

31.	Occupancy	No	
32.	EAST	Vacant waterlogged land	
33.	WEST	House of vidyabushan yadav	
34.	NORTH	Kutchha road 12 feet	
35.	SOUTH	House	
36.	Length of the Road(In Mtr.)	Up to 50 meter	
37.	Existing Width of the Road(In Mtr.)	3.6	
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	3.6	
39.	Width of the RoadWidening(In Mtr.)	0	
40.	Plot area (As per deed)	133.82	

Site Visit Photographs:







Page 2 of 4 Printed on: 12 June, 2020









Recommendation: Verified & found Ok

Remark: Site Inspection done and found okay. Site visit report is attached. Please check for further approval.

Page 3 of 4 Printed on: 12 June, 2020

Deepak Kumar Pandit Junior Engg

Page 4 of 4 Printed on: 12 June, 2020