

Site Inspection

Date: 27/10/2024

1	File No.	Dm/TP/0050/W23/24
2	Owner Name	Sri Subrata Kumar dey, Sri Prabir Kumar dey etc
3	LTP	Rajeev Anand Singh

4 Schedule of Boundaries

East	House
West	House
North	Plot
South	Road

Plot Address	near Kalyani Jewellers, Kola Kusma, Dhanbad
--------------	---

Mouza: Kola Kusma - 12

Khata: 0-113, N-139

Plot: 0-1032/1033, N-753

Area: 441.49 m²

Site Inspection as per Site visit

Road width & Road type: 6.4mtr & Pce


Electric: YES


Drain: NO

Bore: YES

Landmark: Kalyani Jewellers, Kola Kusma

The above mentioned information about the plot is true and Site shown to JE is same for which I had applied for Map approval


(Signature of Land owner)


(Sign of LTP/ LTP staff)