## **Dhanbad Municipal Corporation**

## **SITE VISIT REPORT**

**Proposal Details** 

Owner Name : DEBADUTTA MOHANTY Site Visit Date : 07 June, 2022

Applicant Name : AMIT KUMAR File No. : DMC/BP/0170/W23/2022

Ward No. : W23 Case Type : New

Thana No. : 12 Plot No. OLD - 3493, 3494, NEW - 4282,4283

Road No. / Name : Registration No. : DMC/ENG/0012/2021

2. W 3. Si 4. N 5. W 6. W 7. if n n 8. if cc 9. if w 10. W 11. Le	Description Whether Existing at Site Whether connected with an existing public road Status of road Nature of Road Width of approach road Whether road side drain exists  If Whether road side drain exists is No - Distance from hearest drain  If Whether road side drain exists is No - easibility to connect	As On Site Yes Yes Public Kutchha 6.70 M No 500 M	Objection	Remark
2. W 3. Si 4. N 5. W 6. W 7. if n n 8. if cc 9. if w 10. W 11. Le	Whether connected with an existing public road Status of road Nature of Road Width of approach road Whether road side drain exists  If Whether road side drain exists is No - Distance from hearest drain  If Whether road side drain exists is No - easibility to	Yes Public Kutchha 6.70 M		
3. Si 4. N 5. W 6. W 7. if n 8. if cc 9. if w 10. W 11. Le	Status of road  Nature of Road  Width of approach road  Whether road side drain exists  If Whether road side drain exists is No - Distance from hearest drain  If Whether road side drain exists is No - easibility to	Public Kutchha 6.70 M No		
4. N 5. W 6. W 7. if n n 8. if c c 9. if w 10. W 11. Le	Nature of Road  Vidth of approach road  Whether road side drain exists  If Whether road side drain exists is No - Distance from hearest drain  If Whether road side drain exists is No - easibility to	Kutchha 6.70 M No		
5. W 6. W 7. if no cc 9. if w 10. W 11. Le	Width of approach road  Whether road side drain exists  f Whether road side drain exists is No - Distance from hearest drain  f Whether road side drain exists is No - easibility to	6.70 M No		
6. W 7. if no	Whether road side drain exists  f Whether road side drain exists is No - Distance from nearest drain  f Whether road side drain exists is No - easibility to	No		
7. if no 8. if co 9. if w 10. W 11. Le	f Whether road side drain exists is No - Distance from nearest drain f Whether road side drain exists is No - easibility to			
8. if cc 9. if w 10. W	nearest drain f Whether road side drain exists is No - easibility to	500 M		
9. if w 10. W 11. Le	·			
10. W	UTITICAL	No		
11. Le	f Whether road side drain exists is No - Scope of videning of road	NO		
	Whether the site is at road junction	No		
	evel of site in relation to approach road	ROAD LEVEL		
12. <sub>W</sub>	Whether the area is subject to	NA		
13. <sub>W</sub>	Whether the locality is	Developing		
	Distance of the plot from the nearest temple/ nonument / Airport/ Other important building	200 M		DIST BJP OFFICE
	The vertical and horizontal distance from 33 KV/11 KV electric line	200 M		
16. <sub>W</sub>	Whether the Site is vacant	Yes		
17. PI	Plot size (As per measurement)(In Sqmt)	133.12		
	Whether the applicant encroached the Govt. land/road and/any other land/drainage channel	No		
in ro	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	YES		
20. A	Any other information.	NO		
	/erified the Amins report with/without site inspection and ound correct	Yes		
22. L	Land Use	Residential		
23. R	Road	Yes		
24. S	Sewerage	No		
25. D	Drainage	No		
26. <sub>W</sub>	Vater facility	Yes		
27. A	Availability of drain	No		
28. <sub>Te</sub>	elephone	Yes		
29. EI	Electricity	Yes		
30. D				

Page 1 of 4 Printed on: 09 June, 2022

31.	Occupancy	No
32.	EAST	ROAD
33.	WEST	VACANT LAND
34.	NORTH	UNDER CONSTRUCTION HOUSE
35.	SOUTH	VACANT LAND
36.	Length of the Road(In Mtr.)	Exceeding 250 meter and upto 300 meter
37.	Existing Width of the Road(In Mtr.)	6.7
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	6.7
39.	Width of the RoadWidening(In Mtr.)	0
40.	Plot area (As per deed)	133.59

## **Site Visit Photographs:**







Page 2 of 4 Printed on: 09 June, 2022













Recommendation: Verified & found Ok

**Remark**: Site Inspection done and found okay. Site visit report is attached. Please check for further approval.

Rajesh Kumar Junior Engg

Page 4 of 4 Printed on: 09 June, 2022