

Dhanbad Municipal Corporation

SITE VISIT REPORT


Proposal Details			
Owner Name	: FARKHANDA MIDHAT, MD. SEFULLA	Site Visit Date	: 07 February, 2023
Applicant Name	: KHAN, MD. SOUKAT KHAN, MD. SAHJAD KHAN, MD. SAMSAD KHAN, MD. MANZAR KHAN, MD. SAMSAD KHAN, MD. MANZAR	File No.	: DMC/BP/0022/W23/2023
Ward No.	: W23	Case Type	: New
Thana No.	: 12	Plot No.	: OLD - 156, 157, NEW - 165, 167
Road No. / Name	:	Registration No.	: DMC/ENG/0012/2019




Site Visit Checklist




#	Description	As On Site	Objection	Remark
1.	Whether Existing at Site	Yes		
2.	Whether connected with an existing public road	Yes		
3.	Status of road	Public		
4.	Nature of Road	Blacktop		
5.	Width of approach road	30.0 M		
6.	Whether road side drain exists	Yes		
7.	if Whether road side drain exists is Yes - Width	0.60 M		
8.	if Whether road side drain exists is Yes - Nature	Concrete		
9.	if Whether road side drain exists is Yes - Whether connected to	Public Drain		
10.	Whether the site is at road junction	No		
11.	Level of site in relation to approach road	APPROX 1.0 M BELOW		
12.	Whether the area is subject to	NA		
13.	Whether the locality is	Developing		
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	100 M		
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	5.0 M		HORIZONTAL DISTANCE
16.	Whether the Site is vacant	Yes		TEMPORARY STRUCTURE IS EXISTING ON SITE
17.	Plot size (As per measurement)(In Sqmt)	947.21		
18.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
19.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	YES		
20.	Any other information.	NO		
21.	Verified the Amins report with/without site inspection and found correct	Yes		
22.	Land Use	Commercial		
23.	Road	Yes		
24.	Sewerage	No		
25.	Drainage	No		
26.	Water facility	No		
27.	Availability of drain	Yes		
28.	Telephone	Yes		
29.	Electricity	Yes		



30.	Dealing with inflammable/chemical	No		
31.	Occupancy	No		
32.	EAST	BUILDING		
33.	WEST	VACANT LAND		
34.	NORTH	BUILDING		
35.	SOUTH	ROAD		
36.	Length of the Road(In Mtr.)	Exceeding 1000 meter		
37.	Existing Width of the Road(In Mtr.)	30		
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	30		
39.	Width of the RoadWidening(In Mtr.)	0		
40.	Plot area (As per deed)	971.59		


Site Visit Photographs :













Recommendation : Verified & found Ok

Remark : Site Inspection done and found okay. Temporary structure available on site. Site visit report is attached. Please check for further approval.

Rajesh Kumar
Junior Engg