

Site Inspection Report

Date ..21.../...09.../2024

1.	File No.	DMC/BP/0187/023/24
2.	Owner Name	Paatima Kumari
3.	LTP	Santosh

4. Schedule of Boundaries


East	Road
West	House
North	House
South	Plot

Mouza:	Kolakuroma
Khata:	123/724
Plot:	74/102
Area :	

Plot Address	Near Aajay TVS Show Room Govindpur Road
--------------	---

Site Inspection as per Site visit

Road width & Road type:	4.2m to Pcc
Electric:	NO
Drain:	NO
Water Supply	NO
Landmark:	Near Aajay TVS Show Room



The above mentioned information about the plot is true and Site shown to JE is same for which I had applied for Map approval

FOR *[Signature]*
(Signature of Land owner)

for *[Signature]*
(Sign of LTP/ LTP staff)