JHARKHAND INDUSTRIAL AREA DEVELOPMENT AUTHORITY

SITE VISIT REPORT

Proposal Details

Owner Name : RAMU KUMAR GUPTA Site Visit Date : 06 December, 2019
Applicant Name : RAJIV CHADDA File No. : JIADA/BP/0019/2019

Ward No. : Jasidih Industrial Area Phase II Case Type : New

 Thana No.
 : 209
 Plot No.
 346(p), 347(p), 753(p)

 Road No. / Name
 : jasidih
 Registration No.
 : JIADA/ARC/0006/2019

Site Visit Checklist				
#	Description	As On Site	Objection	Remark
1.	Whether Existing at Site	Yes		
2.	Whether connected with an existing public road	Yes		
3.	Status of road	Public		
4.	Nature of Road	Blacktop		
5.	Width of approach road	30		
ĵ.	Whether road side drain exists	Yes		
7.	if Whether road side drain exists is Yes - Width	0.90		
3.	if Whether road side drain exists is Yes - Nature	Concrete		
9.	if Whether road side drain exists is Yes - Whether connected to	Public Drain		
0.	Whether the site is at road junction	No		
1.	Level of site in relation to approach road	No		
2.	Whether the area is subject to	Affected by drainage channel		
3.	Whether the locality is	Developed		
4.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	No		
5.	The vertical and horizontal distance from 33 KV/11 KV electric line	No		
6.	Whether the Site is vacant	No		
7.	if Whether the Site is vacant No - Stage of construction	1		Completed
8.	if Whether the Site is vacant No - No of Storey	1		
9.	if Whether the Site is vacant No - Nature of construction	AC Shed		
20.	if Whether the Site is vacant No - Sketch enclosed at page	No		
1.	Plot size (As per measurement)(In Sqmt)	4060.29		
2.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
3.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	No		
4.	Any other information.	No		
5.	Verified the Amins report with/without site inspection and found correct	Yes		
6.	Land Use	Industrial		
7.	Road	Yes		
8.	Sewerage	Yes		
9.	Drainage	Yes		
30.	Water facility	Yes		

Page 1 of 3 Printed on : 20 December, 2019

31.	Availability of drain	Yes
32.	Telephone	Yes
33.	Electricity	Yes
34.	Dealing with inflammable/chemical	No
35.	Occupancy	No
36.	EAST	Industrial Plot
37.	WEST	Industrial Plot
38.	NORTH	Road
39.	SOUTH	Pvt Plot
40.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter
41.	Existing Width of the Road(In Mtr.)	30
42.	Proposed Width of the Road as per Master Plan(In Mtr.)	7.5
43.	Width of the RoadWidening(In Mtr.)	0
44.	Plot area (As per deed)	0

Site Visit Photographs:





Page 2 of 3 Printed on: 20 December, 2019







Recommendation: Having Objections & require to raise shortfall

Remark: During the site visit then founded that your Building already Exist.

Jay Prakash Toppo Junior Engg

Page 3 of 3 Printed on: 20 December, 2019