JHARKHAND INDUSTRIAL AREA DEVELOPMENT AUTHORITY

SITE VISIT REPORT

Proposal Details						
Owner Name	: PADMABATI DEVI MULTISPECIALITY	Site Visit Date	: 26 March, 2024			
Applicant Name	HOSPITAL PVT. LTD. REPRESENTED BY	File No.	: JIADA/BP/0015/2022/ALT2			
Ward No.	: Industrial Estate - Adityapur Industrial	Case Type	: Addition Alteration			
Thana No.	: 66,°127	Plot No.	Industrial Plot No. IT-3 & IT-5;			
Road No. / Name	:	Registration No.	: FIATURY ARCT/ 800 7/57918			
Site Visit Checklist						

Description	As On Site	Objection	Remark
Whether Existing at Site	Yes		
Whether connected with an existing public road	Yes		
Status of road	Public		
Nature of Road	Blacktop		
Width of approach road	25		
Whether road side drain exists	Yes		
if Whether road side drain exists is Yes - Width	1		
if Whether road side drain exists is Yes - Nature	Concrete		
if Whether road side drain exists is Yes - Whether connected to	Public Drain		
Whether the site is at road junction	No		
Level of site in relation to approach road	Yes		
	Affected by drainage channel		
Whether the locality is	Developed		
Distance of the plot from the nearest temple/ monument / Airport/ Other important building	NA		
The vertical and horizontal distance from 33 KV/11 KV electric line	NA		
Whether the Site is vacant	Yes		
Plot size (As per measurement)(In Sqmt)	24301.37		
Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Attached		
Any other information.	No		
Verified the Amins report with/without site inspection and found correct	Yes		
Land Use	Industrial		
Road	Yes		
Sewerage	Yes		
Drainage	Yes		
Water facility	Yes		
Availability of drain	Yes		
Telephone	Yes		
Electricity	Yes		
Dealing with inflammable/chemical	No		
	Whether Existing at Site Whether connected with an existing public road Status of road Nature of Road Width of approach road Whether road side drain exists if Whether road side drain exists is Yes - Width if Whether road side drain exists is Yes - Nature if Whether road side drain exists is Yes - Nature if Whether road side drain exists is Yes - Nature if Whether road side drain exists is Yes - Nature if Whether road side drain exists is Yes - Nature if Whether road side drain exists is Yes - Whether connected to Whether the site is at road junction Level of site in relation to approach road Whether the area is subject to Whether the locality is Distance of the plot from the nearest temple/ monument / Airport/ Other important building The vertical and horizontal distance from 33 KV/11 KV electric line Whether the applicant encroached the Govt. land/road land/any other land/drainage channel Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page Any other information. Verified the Amins report with/without site inspection and found correct Land Use	Whether Existing at SiteYesWhether connected with an existing public roadYesStatus of roadPublicNature of RoadBlacktopWidth of approach road25Whether road side drain existsYesif Whether road side drain exists is Yes - Width1if Whether road side drain exists is Yes - NatureConcreteif Whether road side drain exists is Yes - NatureConcreteif Whether road side drain exists is Yes - Whether connected toPublic DrainWhether the site is at road junctionNoLevel of site in relation to approach roadYesWhether the area is subject toAffected by drainage channelWhether the locality isDevelopedDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingNAWhether the Site is vacantYesPlot size (As per measurement)(In Sqmt)24301.37Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNoSketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNoAny other information.NoVerified the Amins report with/without site inspection and found correctYesLand UseIndustrialRoadYesSewerageYesDrainageYesWater facilityYesAvailability of drainYesElephoneYes	Whether Existing at SiteYesWhether connected with an existing public roadYesStatus of roadPublicNature of RoadBlacktopWidth of approach road25Whether road side drain existsYesif Whether road side drain exists is Yes - NatureConcreteif Whether road side drain exists is Yes - NatureConcreteif Whether road side drain exists is Yes - NatureConcreteif Whether road side drain exists is Yes - Whether connected toPublic DrainWhether the site is at road junctionNoLevel of site in relation to approach roadYesWhether the locality isDevelopedDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingNAWhether the Site is vacantYesPlot size (As per measurement)(In Sqmt)24301.37Whether the applicant encroached the Govt. land/road land/ary other land/drainage channelSketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageAny other information.NoVerified the Amins report with/without site inspection and found correctYesLand UseIndustrialRoadYesSewerageYesDrainageYesSewerageYesDrainageYesElephoneYesElephoneYesElephoneYesElephoneYes

31.	Occupancy	No	
32.	EAST	Industrial Road	
33.	WEST	Industrial plot	
34.	NORTH	Industrial plot	
35.	SOUTH	industrial plot	
36.	Length of the Road(In Mtr.)	Up to 50 meter	
37.	Existing Width of the Road(In Mtr.)	25	
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	0	No
39.	Width of the RoadWidening(In Mtr.)	0	No
40.	Plot area (As per deed)	24301.37	

Site Visit Photographs :









Recommendation : Verified & found Ok Remark : verified and found ok

> Jay Prakash Toppo Junior Engg