Form IV

Certificate for Structure Stability (CSS)

Issue Date of CSS

(This sertificate Adheres to Jharkhand Municipal Act 2011, Jharkhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, Jharkhand Industrial Area Development Authority Act, & Jharkhand Building Bye Laws 2016)

Khasel Khatan No. Khas No . S29 Landmark / Locality Street address Thans name / No Ward No Owner / Builder Name Name of Local body 4 SP TI WARY ENTERPRISEGIIAGE Name / Mouza Name JIADA 99 Project / Proposal Type Occupancy Type/Purpose Supervision Certificate (SC) (No) Issue date of Supervision Certificate Date and Time of Application / file Application / file no. Name of Associated Technical Person (if any) BULDING PERMISSION DUSN1 UNDUSTRIAL

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plans and details Including the relevent specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural disasters like cyclone & earth quake sto, as applicable under the Byelaws and stiputated under Part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

f undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed conforming to the structural plan-prepared structural calculations, plans and details including the relevant specifications of the building prepared by

I will be responsible and. Sable for action by (Name of ULB.) Govt of Jharkhand If the plan/ design contain misrepresentation or fraudulent information and the sensitivetion is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural stability of the building structural failure due wrong funsate structural design/ use of low quality material and/ or poor workmanship endangering the safety of immates or public and the

Marie of Structure Engineery ON Engineery OO 13 |2018

Region of ALPEDDIA KRYERI BLOCK

Address ELDI JABE EN VALLE 3,

GLOCK ACANDA TELLO, TRAISHEDPUR, THAPKINN D

Authorized Signatory
(Name of Owner/Bujder)
Registration No.

Address Kers Heat Road, Somesi Janubed pur - 831011