JHARKHAND INDUSTRIAL AREA DEVELOPMENT AUTHORITY

SITE VISIT REPORT

Proposal Details

Owner Name : AGARWAL DYEING represented by MR. Site Visit Date : 10 October, 2023

Applicant Name : Nikhil ain File No. : JIADA/BP/0017/2023

Ward No. : Burmu Case Type : New

Thana No. : 69 Plot No. Survey Plot No. 1353P; Industrial

Road No. / Name : Registration No. : PIADA/ARC/0001/2018

| | Site Visit Checklist | | | | | |
|-----|--|----------------|-----------|--------|--|--|
| # | Description | As On Site | Objection | Remark | | |
| 1. | Whether Existing at Site | Yes | | | | |
| 2. | Whether connected with an existing public road | Yes | | | | |
| 3. | Status of road | Public | | | | |
| 4. | Nature of Road | Blacktop | | | | |
| 5. | Width of approach road | 15.24 | | | | |
| 6. | Whether road side drain exists | No | | | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 500 | | | | |
| 8. | if Whether road side drain exists is No - easibility to connect | Yes | | | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | No | | | | |
| 10. | Whether the site is at road junction | No | | | | |
| 11. | Level of site in relation to approach road | Yes | | | | |
| 12. | Whether the area is subject to | Low lying land | | | | |
| 13. | Whether the locality is | Developed | | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | NA | | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | NA | | | | |
| 16. | Whether the Site is vacant | Yes | | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 6677.31 | | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | Attached | | | | |
| 20. | Any other information. | No | | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | | |
| 22. | Land Use | Industrial | | | | |
| 23. | Road | Yes | | | | |
| 24. | Sewerage | Yes | | | | |
| 25. | Drainage | Yes | | | | |
| 26. | Water facility | Yes | | | | |
| 27. | Availability of drain | Yes | | | | |
| 28. | Telephone | Yes | | | | |
| 29. | Electricity | Yes | | | | |
| 30. | Dealing with inflammable/chemical | No | | | | |

Page 1 of 3 Printed on: 13 October, 2023

| 31. | Occupancy | No | |
|-----|--|-----------------|----|
| 32. | EAST | Pvt. Plot | |
| 33. | WEST | Road | |
| 34. | NORTH | Pvt. Plot | |
| 35. | SOUTH | Industrial Plot | |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter | |
| 37. | Existing Width of the Road(In Mtr.) | 15.24 | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0 | No |
| 39. | Width of the RoadWidening(In Mtr.) | 0 | No |
| 40. | Plot area (As per deed) | 6677.31 | |

Site Visit Photographs:







Page 2 of 3 Printed on: 13 October, 2023



 $\textbf{Recommendation} \ : \ Verified \ \& \ found \ Ok$

Remark: verified and found ok

Jay Prakash Toppo Junior Engg

Page 3 of 3 Printed on: 13 October, 2023