Deoghar Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : RANJANA GUPTA AND SAPANA GUPTA Site Visit Date : 22 May, 2018

Applicant Name : UJJAWAL KUMAR File No. : DGMC/BP/0015/W11/2018

Ward No.: W11Case Type: NewThana No.: 399Plot No.86

Road No. / Name : PURANDAHA Registration No. : DGMC/ENG/0005/2016

Site Visit Checklist				
#	Description	As On Site	Objection	Remark
1.	Approach Road			
2.	Whether Existing at Site	Yes		
3.	Whether connected with an existing public road	Yes		
4.	Status of road	Public		
5.	Nature of Road	Concrete		
6.	Width of approach road	9.14 m		
7.	Whether road side drain exists	Yes		
8.	if Whether road side drain exists is Yes - Width	0.75 m		
9.	if Whether road side drain exists is Yes - Nature	Concrete		
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain		
11.	Site Situation			
12.	Whether the site is at road junction	No		
13.	Level of site in relation to approach road	Leval		
14.	Whether the area is subject to	Affected by drainage channel		
15.	Whether the locality is	Developed		
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	St. Mary girls High school		
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	N/A		
18.	Site Details			
19.	Whether the Site is vacant	Yes		
20.	Plot size (As per measurement)(In Sqmt)	117.68		
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	60 m from St. Mary girls High school		
23.	Any other information.	N/A		
24.	Verification Details			
25.	Verified the Amins report with/without site inspection and found correct	Yes		
26.	Verified the cadastral map			
27.	Land Use	Residential		
28.	Existing off site Physical Infrastructure:			
29.	Road	Yes		
30.	Sewerage	No		

Page 1 of 3 Printed on: 29 May, 2018

F		
31.	Drainage	Yes
32.	Water facility	Yes
33.	Availability of drain	Yes
34.	Telephone	Yes
35.	Electricity	Yes
36.	Risk Parameter	
37.	Dealing with inflammable/chemical	No
38.	Occupancy	No
39.	Site Surrounded by (physical features)	
40.	EAST	PLOT OF SHAILENDRA NATH BANERJEE
41.	WEST	9.14
42.	NORTH	COMMON ROAD
43.	SOUTH	PROPOSED ROAD
44.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter
45.	Existing Width of the Road(In Mtr.)	9.41
46.	Proposed Width of the Road as per Master Plan(In Mtr.)	0
47.	Width of the RoadWidening(In Mtr.)	0

Site Visit Photographs:





Page 2 of 3 Printed on: 29 May, 2018







Recommendation :

Remark :

Junior Engineer
Junior Engg

Page 3 of 3 Printed on: 29 May, 2018