Deoghar Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : SRI RAKESH KUMAR SINGH Site Visit Date : 03 September, 2019
Applicant Name : AASHUTOSH KUMAR File No. : DGMC/0001/2019

Ward No. : W31 Case Type : New

Thana No. : 413 Plot No. 714 (PART)

Road No. / Name : SHYAMGANJ CASTAIR TOWN UMAPATI Registration No. : DGMC/ENG/0018/2017

BANARJEE ROAD DEOGHAR

| | BANARJEE ROAD DEOGHAR | | | | | |
|----------------------|--|-------------------------------------|-----------|--------|--|--|
| Site Visit Checklist | | | | | | |
| # | Description | As On Site | Objection | Remark | | |
| 1. | Whether Existing at Site | Yes | | | | |
| 2. | Whether connected with an existing public road | Yes | | | | |
| 3. | Status of road | Public | | | | |
| 4. | Nature of Road | Blacktop | | | | |
| 5. | Width of approach road | 18.2 | | | | |
| 6. | Whether road side drain exists | Yes | | | | |
| 7. | if Whether road side drain exists is Yes - Width | 0.45 m | | | | |
| 8. | if Whether road side drain exists is Yes - Nature | Concrete | | | | |
| 9. | if Whether road side drain exists is Yes - Whether connected to | Public Drain | | | | |
| 10. | Whether the site is at road junction | No | | | | |
| 11. | Level of site in relation to approach road | -0.15 m | | | | |
| 12. | Whether the area is subject to | NA | | | | |
| 13. | Whether the locality is | Developed | | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | About 50 m from Ram janki mandir | | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | na | | | | |
| 16. | Whether the Site is vacant | Yes | | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 186.23 | | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | Near Prince lodge | | | | |
| 20. | Any other information. | Na | | | | |
| | Verified the Amins report with/without site inspection and found correct | Yes | | | | |
| 22. | Land Use | Residential | | | | |
| 23. | Road | Yes | | | | |
| 24. | Sewerage | No | | | | |
| 25. | Drainage | No | | | | |
| 26. | Water facility | Yes | | | | |
| 27. | Availability of drain | Yes | | | | |
| 28. | Telephone | Yes | | | | |
| 29. | Electricity | Yes | | | | |
| 30. | Dealing with inflammable/chemical | No | | | | |
| 31. | Occupancy | No | | | | |
| | | | | | | |

Page 1 of 3 Printed on : 20 December, 2019

| 32. | EAST | land of chandra ketu singh |
|-----|--|--|
| 33. | WEST | plot of amita devi |
| 34. | NORTH | land of chandraketu singh |
| 35. | SOUTH | plot of umapati banarjee road |
| 36. | Length of the Road(In Mtr.) | Exceeding 300 meter and upto 400 meter |
| 37. | Existing Width of the Road(In Mtr.) | 18.2 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 18.2 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 186.23 |

Site Visit Photographs:







Page 2 of 3 Printed on: 20 December, 2019





Recommendation :

Remark :

Junior Engineer
Junior Engg

Page 3 of 3 Printed on: 20 December, 2019