Deoghar Municipal Corporation

SITE VISIT REPORT

| Prop | osal Details | | | | | | | | | |
|-----------------|---|---|--|-------------------------|---------|--|--|--|--|--|
| Owner Name | | : SRI RAVI KUMAR KESHRI | Site Visit Date | : 16 June, 2020 | | | | | | |
| Applicant Name | | : PINTU KUMAR SINGH | File No. | : DGMC/BP/0012/W19/2020 | | | | | | |
| Ward No. : W19 | | Case Type | : New | | | | | | | |
| Thana No. : 413 | | | Plot No. | 507 MARK A (PART) | | | | | | |
| коас | d No. / Name | : JALSAR ROADNEAR SARITA HOTEL, DEOGHAR | Registration No. | : DGMC/ENG/001 | 14/2017 | | | | | |
| | Site Visit Checklist | | | | | | | | | |
| # | | Description | As On Site | Objection | Remark | | | | | |
| 1. | Whether Existing at Site | | Yes | | | | | | | |
| 2. | Whether connected with an existing public road | | Yes | | | | | | | |
| 3. | Status of road | | Public | | | | | | | |
| 4. | Nature of Road | | Concrete | | | | | | | |
| 5. | Width of approach road | | 3.66m | | | | | | | |
| 6. | Whether road side drain exists | | Yes | | | | | | | |
| 7. | if Whether road side drain exists is Yes - Width | | 0.45m | | | | | | | |
| 8. | if Whether road side drain exists is Yes - Nature | | Concrete | | | | | | | |
| 9. | if Whether road side drain exists is Yes - Whether connected to | | Public Drain | | | | | | | |
| 10. | Whether the site is at road junction | | No | | | | | | | |
| 11. | Level of site in relation to approach road | | -0.3m | | | | | | | |
| 12. | Whether the area is subject to | | NA | | | | | | | |
| 13. | Whether the locality is | | Developed | | | | | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | | Kesharwani Ashram | | | | | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | | NA | | | | | | | |
| 16. | Whether the Site is vacant | | Yes | | | | | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | | 105.91 | | | | | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | | No | | | | | | | |
| 19. | important land | n showing the location of the site, I marks and connectivity with the main ed. (For site not located on main road) at | Kesharwani Ashram is located upto 50m distance from site | | | | | | | |
| 20. | Any other info | rmation. | NA | | | | | | | |
| 21. | Verified the An found correct | nins report with/without site inspection and | Yes | | | | | | | |
| 22. | Land Use | | Residential | | | | | | | |
| 23. | Road | | Yes | | | | | | | |
| 24. | Sewerage | | No | | | | | | | |
| 25. | Drainage | | No | | | | | | | |
| 26. | Water facility | | Yes | | | | | | | |
| 27. | Availability of o | drain | Yes | | | | | | | |
| 28. | Telephone | | Yes | | | | | | | |
| 29. | Electricity | | Yes | | | | | | | |
| 30. | Dealing with ir | nflammable/chemical | No | | | | | | | |
| 31. | Occupancy | | No | | | | | | | |

| 32. | EAST | east | |
|-----|--|----------------|--|
| 33. | WEST | west | |
| 34. | NORTH | north | |
| 35. | SOUTH | south | |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter | |
| 37. | Existing Width of the Road(In Mtr.) | 3.66 | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 3.66 | |
| 39. | Width of the RoadWidening(In Mtr.) | 0 | |
| 40. | Plot area (As per deed) | 105.91 | |

Site Visit Photographs :











Recommendation : Remark :

> Praful Chandra Roy Junior Engg