## Ranchi Zila Parishad

## **SITE VISIT REPORT**

**Proposal Details** 

Owner Name : SRI SURJEET SINGH Site Visit Date : 20 July, 2021

Applicant Name : DIPURAJ SHARMA File No. : RZP/BP/0003/2021

Ward No. : Duli Case Type : New

 Thana No.
 : 10
 Plot No.
 169, 163, 168, 142

 Road No. / Name
 : RZP/ENG/0001/2021

| Site Visit Checklist |  |                      |           |        |  |  |  |
|----------------------|--|----------------------|-----------|--------|--|--|--|
| #                    | Description  | As On Site           | Objection | Remark |  |  |  |
| 1.                   | Whether Existing at Site   | Yes                  |           |        |  |  |  |
| 2.                   | Whether connected with an existing public road   | Yes                  |           |        |  |  |  |
| 3.                   | Status of road   | Private              |           |        |  |  |  |
| 4.                   | Nature of Road   | Kutchha              |           |        |  |  |  |
| 5.                   | Width of approach road   | 12.50 m              |           |        |  |  |  |
| 6.                   | Whether road side drain exists   | No                   |           |        |  |  |  |
| 7.                   | if Whether road side drain exists is No - Distance from nearest drain  | NA                   |           |        |  |  |  |
| 8.                   | if Whether road side drain exists is No - easibility to connect  | No                   |           |        |  |  |  |
| 9.                   | if Whether road side drain exists is No - Scope of widening of road  | NA                   |           |        |  |  |  |
| 10.                  | Whether the site is at road junction   | No                   |           |        |  |  |  |
| 11.                  | Level of site in relation to approach road   | -0.10 M              |           |        |  |  |  |
| 12.                  | Whether the area is subject to   | NA                   |           |        |  |  |  |
| 13.                  | Whether the locality is  | Developing           |           |        |  |  |  |
| 14.                  | Distance of the plot from the nearest temple/<br>monument / Airport/ Other important building  | 500 M FROM<br>TEMPLE |           |        |  |  |  |
| 15.                  | The vertical and horizontal distance from 33 KV/11 KV electric line  | NA                   |           |        |  |  |  |
| 16.                  | Whether the Site is vacant   | Yes                  |           |        |  |  |  |
| 17.                  | Plot size (As per measurement)(In Sqmt)  | 36890                |           |        |  |  |  |
| 18.                  | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel  | No                   |           |        |  |  |  |
| 19.                  | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | 1                    |           |        |  |  |  |
| 20.                  | Any other information.   | NO                   |           |        |  |  |  |
| 21.                  | Verified the Amins report with/without site inspection and found correct   | Yes                  |           |        |  |  |  |
| 22.                  | Land Use   | Residential          |           |        |  |  |  |
| 23.                  | Road   | Yes                  |           |        |  |  |  |
| 24.                  | Sewerage   | Yes                  |           |        |  |  |  |
| 25.                  | Drainage   | Yes                  |           |        |  |  |  |
| 26.                  | Water facility   | Yes                  |           |        |  |  |  |
| 27.                  | Availability of drain  | Yes                  |           |        |  |  |  |
| 28.                  | Telephone  | Yes                  |           |        |  |  |  |
| 29.                  | Electricity  | Yes                  |           |        |  |  |  |
| 30.                  | Dealing with inflammable/chemical  | No                   |           |        |  |  |  |

Page 1 of 3 Printed on: 30 July, 2021

| 31. | Occupancy  | No                                    |  |
|-----|--|---------------------------------------|--|
| 32. | EAST   | MACKLUSKIGANJ<br>ROAD                 |  |
| 33. | WEST   | VACANT PLOT                           |  |
| 34. | NORTH  | DULI SCHOOL                           |  |
| 35. | SOUTH  | DULI VILLAGE                          |  |
| 36. | Length of the Road(In Mtr.)                            | Exceeding 50 meter and upto 100 meter |  |
| 37. | Existing Width of the Road(In Mtr.)                    | 12.5                                  |  |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 12.5                                  |  |
| 39. | Width of the RoadWidening(In Mtr.)                     | 0                                     |  |
| 40. | Plot area (As per deed)                                | 0                                     |  |

## **Site Visit Photographs:**







Page 2 of 3 Printed on: 30 July, 2021





Recommendation: Verified & found Ok

Remark : OK

BALI ORAON Junior Engg

Page 3 of 3 Printed on: 30 July, 2021