Mineral Area Development Authority

SITE VISIT REPORT

Proposal Details

Owner Name : 1. Shambhu Singh 2. Satendra Singh 3. Site Visit Date : 13 November, 2020

Applicant Name : Abhiram Singh File No. : MADA/BP/0030/2020

Ward No. : Kurmidih Case Type : New

Thana No. : 87 Plot No. 1894(Old) 2160(New)
Road No. / Name : Barwa Road, Kurmidih Registration No. : MADA/ENG/0013/2019

Site Visit Checklist				
#	Description	As On Site	Objection	Remark
1.	Whether Existing at Site	Yes		
2.	Whether connected with an existing public road	Yes		
3.	Status of road	Public		
4.	Nature of Road	Kutchha		
5.	Width of approach road	4.25m		
6.	Whether road side drain exists	No		
7.	if Whether road side drain exists is No - Distance from nearest drain	100m		
8.	if Whether road side drain exists is No - easibility to connect	No		
9.	if Whether road side drain exists is No - Scope of widening of road	no		
10.	Whether the site is at road junction	No		
11.	Level of site in relation to approach road	0.01m		
12.	Whether the area is subject to	NA		
13.	Whether the locality is	Developing		
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	Mandir at 300m		
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	7m		
16.	Whether the Site is vacant	Yes		
17.	Plot size (As per measurement)(In Sqmt)	601.76		
18.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
19.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	yes		
20.	Any other information.	n/a		
21.	Verified the Amins report with/without site inspection and found correct	Yes		
22.	Land Use	Residential		
23.	Road	Yes		
24.	Sewerage	No		
25.	Drainage	Yes		
26.	Water facility	Yes		
27.	Availability of drain	Yes		
28.	Telephone	No		
29.	Electricity	Yes		
30.	Dealing with inflammable/chemical	No		

Page 1 of 4 Printed on : 11 November, 2020

31.	Occupancy	No
32.	EAST	ROAD
33.	WEST	VACANT PLOT
34.	NORTH	VACANT PLOT
35.	SOUTH	HOUSE
36.	Length of the Road(In Mtr.)	Up to 50 meter
37.	Existing Width of the Road(In Mtr.)	4.25
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	3.6
39.	Width of the RoadWidening(In Mtr.)	0
40.	Plot area (As per deed)	602

Site Visit Photographs:







Page 2 of 4 Printed on: 11 November, 2020















Recommendation: Verified & found Ok

Remark: Site Inspection redone with correction in plot area and found Okay. Site visit report is attached. Please check for further approval.

Binay Kumar Junior Engg

Page 4 of 4 Printed on: 11 November, 2020