## **Mineral Area Development Authority**

## **SITE VISIT REPORT**

**Proposal Details** 

Owner Name : SRI. RAJKUMAR PRAJAPATI Site Visit Date : 06 April, 2021

Applicant Name : RAM PRATAP SINGH File No. : MADA/BP/0079/2021

Ward No. : Bara Pichri Case Type : New

Thana No. : 129 Plot No. OLD PLOT NO. 501, NEW PLOT NO.

Road No. / Name : 99 SENTOSA GREEN GOVINDPUR ROAD Registration No. : MADA/ARC/0024/2019

| Site Visit Checklist |  |                           |           |                            |
|----------------------|--|---------------------------|-----------|----------------------------|
| #                    | Description  | As On Site                | Objection | Remark                     |
| 1.                   | Whether Existing at Site   | Yes                       |           |                            |
| 2.                   | Whether connected with an existing public road   | Yes                       |           |                            |
| 3.                   | Status of road   | Public                    |           |                            |
| 4.                   | Nature of Road   | Kutchha                   |           |                            |
| 5.                   | Width of approach road   | 6.1m                      |           |                            |
| 6.                   | Whether road side drain exists   | No                        |           |                            |
| 7.                   | if Whether road side drain exists is No - Distance from nearest drain  | 200m                      |           |                            |
| 8.                   | if Whether road side drain exists is No - easibility to connect  | Yes                       |           |                            |
| 9.                   | if Whether road side drain exists is No - Scope of widening of road  | No                        |           |                            |
| 10.                  | Whether the site is at road junction   | Yes                       |           |                            |
| 11.                  | Level of site in relation to approach road   | 0.01m                     |           |                            |
| 12.                  | Whether the area is subject to   | NA                        |           |                            |
| 13.                  | Whether the locality is  | Developing                |           |                            |
| 14.                  | Distance of the plot from the nearest temple/<br>monument / Airport/ Other important building  | Reliance petrol pump 500m |           | Credo world school<br>400m |
| 15.                  | The vertical and horizontal distance from 33 KV/11 KV electric line  | 50m                       |           | transformer 250m           |
| 16.                  | Whether the Site is vacant   | Yes                       |           |                            |
| 17.                  | Plot size (As per measurement)(In Sqmt)  | 103.83                    |           |                            |
| 18.                  | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel  | No                        |           |                            |
| 19.                  | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | Yes                       |           |                            |
| 20.                  | Any other information.   | NA                        |           |                            |
| 21.                  | Verified the Amins report with/without site inspection and found correct   | Yes                       |           |                            |
| 22.                  | Land Use   | Residential               |           |                            |
| 23.                  | Road   | Yes                       |           |                            |
| 24.                  | Sewerage   | No                        |           |                            |
| 25.                  | Drainage   | No                        |           |                            |
| 26.                  | Water facility   | No                        |           |                            |
| 27.                  | Availability of drain  | No                        |           |                            |
| 28.                  | Telephone  | No                        |           |                            |
| 29.                  | Electricity  | No                        |           |                            |
| 30.                  | Dealing with inflammable/chemical  | No                        |           |                            |
|                      | i e e e e e e e e e e e e e e e e e e e  | i .                       | 1         |                            |

Page 1 of 3 Printed on: 05 April, 2021

| 31. | Occupancy  | No             |
|-----|--|----------------|
| 32. | EAST   | Road           |
| 33. | WEST   | Vacant         |
| 34. | NORTH  | Vacant         |
| 35. | SOUTH  | Vacant         |
| 36. | Length of the Road(In Mtr.)                            | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.)                    | 6.1            |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 6.1            |
| 39. | Width of the RoadWidening(In Mtr.)                     | 0              |
| 40. | Plot area (As per deed)                                | 104.04         |

## **Site Visit Photographs:**







Page 2 of 3 Printed on: 05 April, 2021







Recommendation: Verified & found Ok

**Remark**: Site Inspection done and found Okay. Site visit report is attached. Please check for further approval.

Binay Kumar Junior Engg

Page 3 of 3 Printed on: 05 April, 2021