## **Mineral Area Development Authority**

## **SITE VISIT REPORT**

**Proposal Details** 

Owner Name : SRI BAL KRISHNA TRIPATHI Site Visit Date : 07 October, 2023

Applicant Name : Lalan Prasad Singh File No. : MADA/BP/0237/2023

Ward No. : Tetulia Case Type : New

 Thana No.
 : 38
 Plot No.
 NEW-656,OLD-163

 Road No. / Name
 :
 Registration No.
 : MADA/ENG/0001/2020

Site Visit Checklist						
#	Description	As On Site	Objection	Remark		
1.	Whether Existing at Site	Yes				
2.	Whether connected with an existing public road	Yes				
3.	Status of road	Public				
4.	Nature of Road	Blacktop				
5.	Width of approach road	12.19				
6.	Whether road side drain exists	Yes				
7.	if Whether road side drain exists is Yes - Width	0.60 M				
8.	if Whether road side drain exists is Yes - Nature	Concrete				
9.	if Whether road side drain exists is Yes - Whether connected to	OutFall				
10.	Whether the site is at road junction	No				
11.	Level of site in relation to approach road	ROAD LEVEL				
12.	Whether the area is subject to	NA				
13.	Whether the locality is	Developing				
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	20 M		GARGA BRIDGE BARI CO-OPERATIVE		
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	50 M				
16.	Whether the Site is vacant	No		Site Inspection done and found old RCC constructed building. Demolition affidavit is attached by owner.		
17.	if Whether the Site is vacant No - Stage of construction	1				
18.	if Whether the Site is vacant No - No of Storey	1				
19.	if Whether the Site is vacant No - Nature of construction	RCC				
20.	if Whether the Site is vacant No - Sketch enclosed at page	No				
21.	Plot size (As per measurement)(In Sqmt)	404.79				
22.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No				
23.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	YES				
24.	Any other information.	NO				
25.	Verified the Amins report with/without site inspection and found correct	No				
26.	If No, Reason	N/A				
27.	Land Use	Residential				
28.	Road	Yes				

Page 1 of 7 Printed on: 07 October, 2023

29.	Sewerage	No	
30.	Drainage	No	
31.	Water facility	Yes	
32.	Availability of drain	Yes	
33.	Telephone	Yes	
34.	Electricity	Yes	
35.	Dealing with inflammable/chemical	No	
36.	Occupancy	No	
37.	EAST	VACANT LAND	
38.	WEST	ROAD	
39.	NORTH	LAXMI BIKE & CAR WASHING	
40.	SOUTH	EXISTING BUILDING	
41.	Length of the Road(In Mtr.)	Exceeding 1000 meter	
42.	Existing Width of the Road(In Mtr.)	12.19	
43.	Proposed Width of the Road as per Master Plan(In Mtr.)	7.5	
44.	Width of the RoadWidening(In Mtr.)	0	
45.	Plot area (As per deed)	404.83	10.0 DISMIL

## Site Visit Photographs:





Page 2 of 7 Printed on: 07 October, 2023





































Recommendation: Verified & found Ok

**Remark**: Site Inspection done and found old RCC constructed building. Demolition affidavit is attached by owner. Site visit report is attached. Please check for further approval.

Shivshanker Kumar Ray Junior Engg

Page 7 of 7 Printed on: 07 October, 2023