Mineral Area Development Authority

Г

SITE VISIT REPORT

| Proposal Details | | | | | | |
|------------------|----------------------|------------------|----------------------|--|--|--|
| Owner Name | : VIKASH KUMAR YADAV | Site Visit Date | : 19 April, 2024 | | | |
| Applicant Name | : AMIT KUMAR | File No. | : MADA/BP/0133/2024 | | | |
| Ward No. | : Narayanpur | Case Type | : New | | | |
| Thana No. | : 13 | Plot No. | OLD - 334, NEW - 103 | | | |
| Road No. / Name | : | Registration No. | : MADA/ENG/0008/2021 | | | |


| | Site Visit | Checklist | | |
|-----|---|---|-----------|--------|
| # | Description | As On Site | Objection | Remark |
| 1. | Whether Existing at Site | Yes | | |
| 2. | Whether connected with an existing public road | Yes | | |
| 3. | Status of road | Public | | |
| 4. | Nature of Road | Kutchha | | |
| 5. | Width of approach road | 4.57 | | |
| 6. | Whether road side drain exists | No | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 250 | | |
| 8. | if Whether road side drain exists is No - easibility to connect | No | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | 0.25 | | |
| 10. | Whether the site is at road junction | No | | |
| 11. | Level of site in relation to approach road | -0.25 | | |
| 12. | Whether the area is subject to | NA | | |
| 13. | Whether the locality is | Developing | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | Back of mandir from 300 mt dibra bera | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | na | | |
| 16. | Whether the Site is vacant | Yes | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 204.14 | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | Yes | | |
| 20. | Any other information. | na | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | |
| 22. | Land Use | Residential | | |
| 23. | Road | No | | |
| 24. | Sewerage | No | | |
| 25. | Drainage | No | | |
| 26. | Water facility | No | | |
| 27. | Availability of drain | No | | |
| 28. | Telephone | No | | |
| 29. | Electricity | No | | |

| 30. | Dealing with inflammable/chemical | No |
|-----|--|---|
| 31. | Occupancy | No |
| 32. | EAST | N.K. PRASAD, PLOT NO. 857 |
| 33. | WEST | KAPIL DEV RAM, PART OF PLOT NO. 103 |
| 34. | NORTH | PLOT NO. 101 |
| 35. | SOUTH | 4.57 Road |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.) | 4.57 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 3.6 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 204.14 |

Site Visit Photographs :







Recommendation : Verified & found Ok Remark : Site Inspection done and found okay. Site visit report is attached. Please check for further approval.

Kaushlesh Kumar Yadav Junior Engg