

## Site Inspection

1. File No.	P-1001/100/200/200
2. Owner Name	Suresh Aggarwal
3. LTR	Amrit Kumar Chawla

### 4. Address of Structure

Loc:

Top floor 2 (Ground floor  
2nd floor (upper floor)  
Ground level  
R.T.O.

5. Address

Pitampura, Colony garden, New Delhi, India  
Area: Dwarka

Block: 2101, MP (New)  
Plot: 11 (Total, 10 plots)

6. Date:

### Site Inspection Report Date:


Date: 10/10/2001 By: P.K. Rao

Structure: 100

Floor: 2nd

Area: 400

Address: Pitampura



The above mentioned dimensions about the plot area and the drawing is to be used for construction against the same.

Signature: \_\_\_\_\_

(Signature of Surveyor / Owner Developer)

Signature: \_\_\_\_\_

(Signature of Surveyor / Owner Developer)