Mineral Area Development Authority

SITE VISIT REPORT

Proposal Details

Owner Name : 1) MAKSUD ALAM, (2)SHABIHA BEGAM Site Visit Date : 05 July, 2024

Applicant Name : Ashish kumar singh File No. : MADA/BP/0254/2024

Ward No. : Karmatand Case Type : New

Thana No. : 175 Plot No. NEW -1256,1257, OLD -877,878,888

Road No. / Name : Registration No. : MADA/ARC/0028/2019

| | Site Visit Checklist | | | | |
|-----|--|-----------------------------|-----------|--------|--|
| # | Description | As On Site | Objection | Remark | |
| 1. | Whether Existing at Site | Yes | | | |
| 2. | Whether connected with an existing public road | Yes | | | |
| 3. | Status of road | Public | | | |
| 4. | Nature of Road | Kutchha | | | |
| 5. | Width of approach road | 6.7 | | | |
| 6. | Whether road side drain exists | No | | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 150 | | | |
| 8. | if Whether road side drain exists is No - easibility to connect | No | | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | na | | | |
| 10. | Whether the site is at road junction | No | | | |
| 11. | Level of site in relation to approach road | -0.25 | | | |
| 12. | Whether the area is subject to | NA | | | |
| 13. | Whether the locality is | Developing | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 150 mtr from JAMA MASJID | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | NA | | | |
| 16. | Whether the Site is vacant | Yes | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 117.14 | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | YES | | | |
| 20. | Any other information. | NA | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | |
| 22. | Land Use | Residential | | | |
| 23. | Road | Yes | | | |
| 24. | Sewerage | No | | | |
| 25. | Drainage | No | | | |
| 26. | Water facility | No | | | |
| 27. | Availability of drain | No | | | |
| 28. | Telephone | No | | | |
| 29. | Electricity | No | | | |
| 30. | Dealing with inflammable/chemical | No | | | |

Page 1 of 3 Printed on: 03 July, 2024

| 31. | Occupancy | No |
|-----|--|-----------------|
| 32. | EAST | 6.7 M WIDE ROAD |
| 33. | WEST | HOUSE NO - 19 |
| 34. | NORTH | HOUSE NO - 14 |
| 35. | SOUTH | HOUSE NO - 12 |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.) | 6.7 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 5.1 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 2429.27 |

Site Visit Photographs:







Page 2 of 3 Printed on: 03 July, 2024





Recommendation: Verified & found Ok

Remark:

Site measurement and road width verification done by JE.Report is prepared and attached along with site photograph by JE.

File is being forwarded to authority for further approval.

Kaushlesh Kumar Yadav Junior Engg

Page 3 of 3 Printed on: 03 July, 2024