

Site Inspection

Date: 21/05/2024



1	File No.	MADA/BP/0085/2024
2	Owner Name	Smt. Arti Singh.
3	LTP	Sri Kam Pratap Singh.

4 Schedule of Boundaries

East	Road
West	Same Plot
North	Road
South	Same Plot.

Plot Address	Sentosa Green
--------------	---------------

Mouza: Jialgora
Khata: Old:- 34, New:- 5
Plot: Old:- 522, New:- 129
Area: 93.11 Sqmt.



Site Inspection as per Site visit

Road width & Road type: 20' wide road Kacheheri.
Electric: NO
Drain: NO
Bore: NO
Landmark: under sentosa green

The above mentioned information about the plot is true and Site shown to JE is same for which I had applied for Map approval

Arti Singh
(Signature of Land owner)

21/5/24
SDO

Akash Kumar
(Sign of LTP/ LTP staff)