

# Site Inspection

1 File No.	MADA/BP/0329/2024
2 Owner Name	Sri Daroga Kumar
3 LTP	Abhishek Kumar

Date: \_\_\_/\_\_\_/2022

### 4 Schedule of Boundaries

East	Road
West	Plot
North	Road 4.724M
South	Plot

Plot Address	Narayanpur, Dhengi More, Kolaru mca
--------------	-------------------------------------

Mouza: Narayanpur

Khata: New-80, Old-34

Plot: New-676, Old-618772

Area: 267.18 (Area after road.) 265, Site as per site

### Site Inspection as per Site visit


Road width & Road type: 15'-6" 11

Electric: yes


Drain: NO

Bore: yes

Landmark: Pushpa Place



The above mentioned information about the plot is true and Site shown to JE is same for which I had applied for Map approval

  
 (Signature of Land owner)

  
 (Sign of LTP/ LTP staff)